



CUADRO DE COORDENADAS DEL TABLERO		
PUNTO	NORTE	ESTE
1	967426.7796	920359.4093
2	967451.7467	920360.6916
3	967449.6950	920400.6390
4	967424.7279	920399.3566

CUADRO DE COORDENADAS DE EJES		
PUNTO	NORTE	ESTE
A	967439.4629	920360.0607
B	967437.4111	920400.0081